UNITED STATES GOVERNMENT Appropries For Release 2003/05/06: CIA-RDP87-00558R000100040047-2 TO Chief, Supply Division, OL KO DATE: 13 September 1976 Chief, Supply Management Branch, SD/OL ATTN Deputy Chief, STAT SUBJECT: Inspection of Hillside Class #6 Security Cabinet STAT In response to a request made by the leader of Team "C", safe technician at STAT performed STAT an initial inspection of four each, Hillside Class #6 Security Cabinets. This was done because of the past poor performance of Hillside Cabinets and the Office of Security's reluctance to accept them for issue. 2. Mr. report and associated photographs are STAT attached. STAT Atts: 9/20/76 STAT TELECON



Administrative - Internal Use Only

Buy U.S. Savings Bonds Regularly on the Payroll Savings Plan

Inspection on Hillside Class #6 Security Cabinet (At Safe Shop
Combination Lock: 1. Lock mounting plate loose which causes the lock to shift.
2. Hard plates in front of lock case are loose and could cause hard plates to cut into the outer spindle and it could cause it to break in half.
Drawer Stops Draw stop on the side of the draw which is called the drawer body slide are set too high and would cause a safety problem and should be considered a safety hazard.
Bolts and Handle Bolt cam will clear the bolt lock when the arber is removed from the cam without retracting the lock bolt.
Drawer Suspension Drawer suspensions are not sturdy enough to carry the weight load as the weight is down and would cause the suspension to buckle and bind on the drawer.
Safe Technician

STAT